

Dolan Chemical Laboratory 4001 Bixby Road Groveport, OH 43125 T: 614-836-4221, Audinet 210-4221 F: 614-836-4168, Audinet 210-4168 http://aepenv/labs

Water Analysis

Location: Mountaineer Plant

Report Date: 1/17/2013

1	st	S	ta	a	e	F	e	e	h	

Sample Number: 130120-00	1 Date Col	Date Collected:		08:00	Date Received: 1/9/2013	
Parameter	Result Units	RL	MDL	Analysis By	Analysis Date/Time	Method
Selenium, Se	363 ug/L	0.50	0.20	DPC	01/16/2013 12:14	EPA 200.8

2nd Stage Feed

Sample Number:	130120-002	D	Date Collected:	01/09/2013	08:00	Date Received: 1/9	/2013
Parameter		Result U	Inits RL	MDL	Analysis By	Analysis Date/Time	Method
Selenium, Se		127 սզ	g/L 0.50	0.20	DPC	01/16/2013 12:18	EPA 200.8

Bioreactor Effluent

Sample Number:	130120-003	Date Co	llected: (01/09/2013	08:00	Date Received: 1/9	/2013
Parameter		Result Units	RL	MDL	Analysis By	Analysis Date/Time	Method
Selenium, Se		3.0 ug/L	0.50	0.20	DPC	01/16/2013 12:23	EPA 200.8

Brian Snyder, Chemist II

Email bssnyder@aep.com Tel. 614-836-4224
Fax 614-836-4168 Audinet 210-4224

THIS TEST REPORT RELATES ONLY TO THE ITEMS TESTED AND SHALL NOT BE REPRODUCED EXCEPT IN FULL WITHOUT WRITTEN APPROVAL OF THE LABORATORY. ALL TEST RESULTS MEET ALL OF THE REQUIREMENTS OF THE ACCREDITING AUTHORITY, UNLESS OTHERWISE NOTED.